Cold Chisel, Punches, etc.

Types of Tools

- Cold Chisel
- Punch
- Embossing Tool
- Sharpening Guide
- Tool Steel
- CR-V
- Hammers
  - Claw
  - Ball Pein

Safe and Effective Use

- Wear safety glasses,
- Use a chisel that's 25 percent wider than what you're cutting.
- Use a ball-pein hammer. Never hit anything made from hardened steel with a claw hammer.
- Sharpen the chisel to a 60- to 70-degree bevel. It takes just a few seconds on a grinder to refresh the cutting edges. Use the guide in the chisel set.
- Don't use a chisel with a damaged end striking end. Grind off any curled metal before it splinters off.
- Apply a drop of oil to the cutting edges before use. This reduces friction, which increases the tool's cutting ability.
- Position the work-piece in the middle of the jaws and tighten the vise firmly.
- To maximize the power of each strike, align the chisel with the vise's screw and cut perpendicular to the jaws.
- Never use a chisel (or a file) as a pry-bar.